Fireplace Inspection and Measurement Report

272 1st Street East • North Vancouver V7L 1B3

Sep 26, 2025, 3:51pm PDT

Kirkstone Heating Ltd.
272 1st St E • North Vancouver, BC V7L 1B3
604-764-9009

Fireplace inspection at Customer's House

- Gas oil is malfunctioning
- Corrosion observed on the pilot assembly





Viewing area condition and measurements

- Viewing area is in good condition with no problems
- Small chip present
- Measurements are 38 by 36



Measurement process

- Proceed with measuring as discussed